

OMES rapport 2016

BIJLAGEN

Onderzoek naar de gevolgen van het Sigmaplan,
baggeractiviteiten en havenuitbreiding in de Zeeschelde op het
milieu

monitoring in opdracht van
Waterwegen & Zeekanaal NV
bestek 16EI/14/51



**Ecosystem Management
Research Group (Ecobe)**
University of Antwerp



**Universiteit
Antwerpen**



EcoLab
Laboratoire écologie et fonctionnalité
et environnement



IMDC
International Marine & Dredging Consultants




**VRIJE
UNIVERSITEIT
BRUSSEL**

BIJLAGEN bij het OMES rapport 2016.

Deze bijlage bevat gedetailleerde figuren en tabellen van de profielmetingen opgesteld tijdens de verschillende meetcampagnes uitgevoerd in 2016. Deze profielen voor waterstand, zwevende stofconcentratie en stroomsnelheid werden opgesteld door IMDC.

1.1. Resultaten van de maandelijkse monitoring

1.1.1. Profielresultaten voor de ADCP-metingen



Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Liefkenshoek - 002



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Kallo - 003



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Antwerpen - 004



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Kruibeke - 005



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Bazel - 021



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Steendorp - 006



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Temse - 007



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Nete - 008



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Dijle - 009



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Terhagen - 010



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Boom - 011



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Niel - 012



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Lippenbroek - 013



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Baasrode - 014



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Dendermonde - 015



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

St. Onolfs - 016



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Appelsveer - 017



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Uitbergen - 018



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Wetteren - 019



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

ADCP

Location:

Melle - 020



Date :


20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

1.1.2. Profielresultaten voor de troebelheidsmeter



Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Liefkenshoek - 002



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Kallo - 003



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Antwerpen - 004



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Kruibeke - 005



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Bazel - 021



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Steendorp - 006



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Temse - 007



Date :

18/01/2016 - 12/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Nete - 008



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Dijle - 009



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Terhagen - 010



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Boom - 011



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Niel - 012



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Lippenbroek - 013



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Baasrode - 014



Date :

19/01/2016 - 13/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Dendermonde - 015



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Sint-Onolfs - 016



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Appels - 017



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Uitbergen - 018



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Wetteren - 019



Date :

20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

Onderzoek Milieu-Effecten Sigmaplan (OMES)


11459

Equipment(s):

CTD-OBS

Location:

Melle - 020



Date :


20/01/2016 - 14/12/2016

Data Processed by:



I/RA/11459/17.034/YDK

1.1.3. ADCP-raaimetingen



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_019.csv

Transect ID:

001



Date/time:

15-Feb-2016

09:26 - 09:30

Time after HW:

2:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_019.csv

Transect ID:

001



Date/time:

15-Feb-2016

09:27 - 09:30

Time after HW:

2:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_021.csv

Transect ID:

001



Date/time:

04-Apr-2016

07:03 - 07:07

Time after HW:

1:15

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_022.csv

Transect ID:

001



Date/time:

18-Apr-2016

06:56 - 07:02

Time after HW:

0:29

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_023.csv

Transect ID:

001



Date/time:

09-May-2016

07:02 - 07:08

Time after HW:

3:25

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_024.csv

Transect ID:

001



Date/time:

23-May-2016

07:25 - 07:31

Time after HW:

4:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_025.csv

Transect ID:

001



Date/time:

13-Jun-2016

07:26 - 07:32

Time after HW:

-1:10

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_026.csv

Transect ID:

001



Date/time:

27-Jun-2016

07:15 - 07:22

Time after HW:

0:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_027.csv

Transect ID:

001



Date/time:

12-Jul-2016

07:29 - 07:35

Time after HW:

-0:07

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_028.csv

Transect ID:

001



Date/time:

25-Jul-2016

07:31 - 07:37

Time after HW:

1:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_029.csv

Transect ID:

001



Date/time:

08-Aug-2016

07:35 - 07:41

Time after HW:

1:58

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_030.csv

Transect ID:

001



Date/time:

22-Aug-2016

07:19 - 07:28

Time after HW:

2:33

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_031.csv

Transect ID:

001



Date/time:

05-Sep-2016

07:10 - 07:17

Time after HW:

2:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_032.csv

Transect ID:

001



Date/time:

19-Sep-2016

07:23 - 07:29

Time after HW:

3:46

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Grens

Equipment:



ADCP

Sourcefile:

T_001_035.csv

Transect ID:

001



Date/time:

12-Dec-2016

08:28 - 08:34

Time after HW:

-4:08

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_018.csv

Transect ID:

002



Date/time:

18-Jan-2016

09:55 - 09:58

Time after HW:

1:27

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_019.csv

Transect ID:

002



Date/time:

15-Feb-2016

08:59 - 09:05

Time after HW:

1:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_021.csv

Transect ID:

002



Date/time:

04-Apr-2016

07:37 - 07:40

Time after HW:

1:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_022.csv

Transect ID:

002



Date/time:

18-Apr-2016

07:31 - 07:35

Time after HW:

1:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_023.csv

Transect ID:

002



Date/time:

09-May-2016

07:37 - 07:41

Time after HW:

3:59

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_024.csv

Transect ID:

002



Date/time:

23-May-2016

08:01 - 08:04

Time after HW:

4:53

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_025.csv

Transect ID:

002



Date/time:

13-Jun-2016

07:58 - 08:03

Time after HW:

-0:49

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_026.csv

Transect ID:

002



Date/time:

27-Jun-2016

07:50 - 07:54

Time after HW:

0:52

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_027.csv

Transect ID:

002



Date/time:

12-Jul-2016

08:02 - 08:05

Time after HW:

0:14

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_028.csv

Transect ID:

002



Date/time:

25-Jul-2016

08:11 - 08:16

Time after HW:

2:24

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_028.csv

Transect ID:

002



Date/time:

25-Jul-2016

08:12 - 08:16

Time after HW:

2:24

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_029.csv

Transect ID:

002



Date/time:

08-Aug-2016

08:18 - 08:23

Time after HW:

2:40

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_029.csv

Transect ID:

002



Date/time:

08-Aug-2016

08:20 - 08:23

Time after HW:

2:41

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_030.csv

Transect ID:

002



Date/time:

22-Aug-2016

08:08 - 08:15

Time after HW:

3:32

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_031.csv

Transect ID:

002



Date/time:

05-Sep-2016

07:42 - 07:46

Time after HW:

3:14

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_032.csv

Transect ID:

002



Date/time:

19-Sep-2016

08:03 - 08:08

Time after HW:

4:26

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Liefkenshoek

Equipment:



ADCP

Sourcefile:

T_002_035.csv

Transect ID:

002



Date/time:

12-Dec-2016

09:09 - 09:13

Time after HW:

2:01

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_018.csv

Transect ID:

004



Date/time:

18-Jan-2016

11:14 - 11:16

Time after HW:

2:25

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_019.csv

Transect ID:

004



Date/time:

15-Feb-2016

10:02 - 10:03

Time after HW:

2:33

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_020.csv

Transect ID:

004



Date/time:

14-Mar-2016

09:54 - 09:56

Time after HW:

3:35

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_021.csv

Transect ID:

004



Date/time:

04-Apr-2016

08:31 - 08:32

Time after HW:

2:12

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_022.csv

Transect ID:

004



Date/time:

18-Apr-2016

08:30 - 08:32

Time after HW:

1:31

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_023.csv

Transect ID:

004



Date/time:

09-May-2016

08:37 - 08:39

Time after HW:

4:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_024.csv

Transect ID:

004



Date/time:

23-May-2016

08:57 - 08:59

Time after HW:

5:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_025.csv

Transect ID:

004



Date/time:

13-Jun-2016

08:55 - 08:57

Time after HW:

-0:13

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_026.csv

Transect ID:

004



Date/time:

27-Jun-2016

08:38 - 08:39

Time after HW:

1:19

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_027.csv

Transect ID:

004



Date/time:

12-Jul-2016

09:01 - 09:03

Time after HW:

0:52

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_028.csv

Transect ID:

004



Date/time:

25-Jul-2016

09:26 - 09:29

Time after HW:

3:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_029.csv

Transect ID:

004



Date/time:

08-Aug-2016

09:38 - 09:41

Time after HW:

3:40

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_030.csv

Transect ID:

004



Date/time:

22-Aug-2016

09:33 - 09:36

Time after HW:

4:45

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_031.csv

Transect ID:

004



Date/time:

05-Sep-2016

08:38 - 08:40

Time after HW:

3:59

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_032.csv

Transect ID:

004



Date/time:

19-Sep-2016

09:04 - 09:06

Time after HW:

5:15

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Antwerpen

Equipment:



ADCP

Sourcefile:

T_004_035.csv

Transect ID:

004



Date/time:

12-Dec-2016

10:19 - 10:22

Time after HW:

-2:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_018.csv

Transect ID:

005



Date/time:

18-Jan-2016

11:58 - 12:00

Time after HW:

2:39

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_019.csv

Transect ID:

005



Date/time:

15-Feb-2016

10:33 - 10:35

Time after HW:

2:34

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_020.csv

Transect ID:

005



Date/time:

14-Mar-2016

10:32 - 10:34

Time after HW:

3:33

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_021.csv

Transect ID:

005



Date/time:

04-Apr-2016

09:01 - 09:03

Time after HW:

2:02

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_021.csv

Transect ID:

005



Date/time:

04-Apr-2016

09:02 - 09:03

Time after HW:

2:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_022.csv

Transect ID:

005



Date/time:

18-Apr-2016

08:59 - 09:01

Time after HW:

-4:09

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_023.csv

Transect ID:

005



Date/time:

09-May-2016

09:10 - 09:13

Time after HW:

4:32

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_024.csv

Transect ID:

005



Date/time:

23-May-2016

09:30 - 09:32

Time after HW:

5:31

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_025.csv

Transect ID:

005



Date/time:

13-Jun-2016

09:25 - 09:26

Time after HW:

-0:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_026.csv

Transect ID:

005



Date/time:

27-Jun-2016

09:11 - 09:13

Time after HW:

1:22

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_027.csv

Transect ID:

005



Date/time:

12-Jul-2016

09:31 - 09:33

Time after HW:

1:02

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_028.csv

Transect ID:

005



Date/time:

25-Jul-2016

10:11 - 10:13

Time after HW:

3:22

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_029.csv

Transect ID:

005



Date/time:

08-Aug-2016

10:19 - 10:22

Time after HW:

3:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_029.csv

Transect ID:

005



Date/time:

08-Aug-2016

10:20 - 10:22

Time after HW:

3:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_030.csv

Transect ID:

005



Date/time:

22-Aug-2016

10:20 - 10:24

Time after HW:

4:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_031.csv

Transect ID:

005



Date/time:

05-Sep-2016

09:11 - 09:13

Time after HW:

3:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_032.csv

Transect ID:

005



Date/time:

19-Sep-2016

09:40 - 09:42

Time after HW:

5:11

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_033.csv

Transect ID:

005



Date/time:

17-Oct-2016

09:48 - 09:49

Time after HW:

6:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Kruibeke

Equipment:



ADCP

Sourcefile:

T_005_035.csv

Transect ID:

005



Date/time:

12-Dec-2016

10:55 - 10:58

Time after HW:

-2:33

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_018.csv

Transect ID:

007



Date/time:

18-Jan-2016

13:19 - 13:20

Time after HW:

3:39

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_019.csv

Transect ID:

007



Date/time:

15-Feb-2016

11:38 - 11:40

Time after HW:

3:19

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_020.csv

Transect ID:

007



Date/time:

14-Mar-2016

11:43 - 11:44

Time after HW:

4:23

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_021.csv

Transect ID:

007



Date/time:

04-Apr-2016

10:07 - 10:09

Time after HW:

-2:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_021.csv

Transect ID:

007



Date/time:

04-Apr-2016

10:08 - 10:09

Time after HW:

-2:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_022.csv

Transect ID:

007



Date/time:

18-Apr-2016

09:58 - 10:00

Time after HW:

-3:30

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_022.csv

Transect ID:

007



Date/time:

18-Apr-2016

09:59 - 10:00

Time after HW:

-3:29

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_023.csv

Transect ID:

007



Date/time:

09-May-2016

10:18 - 10:19

Time after HW:

5:19

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_024.csv

Transect ID:

007



Date/time:

23-May-2016

10:59 - 11:00

Time after HW:

6:40

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_025.csv

Transect ID:

007



Date/time:

13-Jun-2016

10:29 - 10:30

Time after HW:

0:50

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_026.csv

Transect ID:

007



Date/time:

27-Jun-2016

10:16 - 10:18

Time after HW:

2:17

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_027.csv

Transect ID:

007



Date/time:

12-Jul-2016

10:37 - 10:39

Time after HW:

1:48

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_028.csv

Transect ID:

007



Date/time:

25-Jul-2016

11:51 - 11:52

Time after HW:

4:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_029.csv

Transect ID:

007



Date/time:

08-Aug-2016

11:35 - 11:36

Time after HW:

4:46

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_030.csv

Transect ID:

007



Date/time:

22-Aug-2016

11:41 - 11:43

Time after HW:

5:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_031.csv

Transect ID:

007



Date/time:

05-Sep-2016

10:09 - 10:10

Time after HW:

4:40

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_032.csv

Transect ID:

007



Date/time:

19-Sep-2016

10:39 - 10:40

Time after HW:

5:50

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_033.csv

Transect ID:

007



Date/time:

17-Oct-2016

11:00 - 11:01

Time after HW:

-5:08

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Temse

Equipment:



ADCP

Sourcefile:

T_007_035.csv

Transect ID:

007



Date/time:

12-Dec-2016

12:03 - 12:04

Time after HW:

-1:45

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_018.csv

Transect ID:

010



Date/time:

19-Jan-2016

09:43 - 09:44

Time after HW:

4:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_019.csv

Transect ID:

010



Date/time:

16-Feb-2016

10:00 - 10:01

Time after HW:

0:30

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_021.csv

Transect ID:

010



Date/time:

05-Apr-2016

09:01 - 09:02

Time after HW:

-5:08

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_022.csv

Transect ID:

010



Date/time:

19-Apr-2016

09:20 - 09:21

Time after HW:

-5:09

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_023.csv

Transect ID:

010



Date/time:

10-May-2016

09:48 - 09:51

Time after HW:

3:49

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_025.csv

Transect ID:

010



Date/time:

14-Jun-2016

08:54 - 08:55

Time after HW:

-1:54

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_026.csv

Transect ID:

010



Date/time:

28-Jun-2016

08:43 - 08:44

Time after HW:

-0:36

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_027.csv

Transect ID:

010



Date/time:

13-Jul-2016

08:41 - 08:43

Time after HW:

-1:17

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_029.csv

Transect ID:

010



Date/time:

09-Aug-2016

08:45 - 08:46

Time after HW:

1:06

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_030.csv

Transect ID:

010



Date/time:

23-Aug-2016

08:42 - 08:43

Time after HW:

1:43

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_031.csv

Transect ID:

010



Date/time:

06-Sep-2016

09:13 - 09:14

Time after HW:

2:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_032.csv

Transect ID:

010



Date/time:

20-Sep-2016

08:57 - 08:58

Time after HW:

2:58

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_033.csv

Transect ID:

010



Date/time:

18-Oct-2016

09:10 - 09:11

Time after HW:

4:21

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Terhagen

Equipment:



ADCP

Sourcefile:

T_010_035.csv

Transect ID:

010



Date/time:

13-Dec-2016

10:15 - 10:17

Time after HW:

-4:33

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_018.csv

Transect ID:

013



Date/time:

19-Jan-2016

11:44 - 11:45

Time after HW:

0:54

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_019.csv

Transect ID:

013



Date/time:

16-Feb-2016

12:02 - 12:04

Time after HW:

2:43

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_020.csv

Transect ID:

013



Date/time:

15-Mar-2016

12:05 - 12:06

Time after HW:

3:56

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_021.csv

Transect ID:

013



Date/time:

05-Apr-2016

10:49 - 10:50

Time after HW:

-3:09

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_022.csv

Transect ID:

013



Date/time:

19-Apr-2016

11:09 - 11:10

Time after HW:

-3:09

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_023.csv

Transect ID:

013



Date/time:

10-May-2016

12:03 - 12:06

Time after HW:

6:15

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_024.csv

Transect ID:

013



Date/time:

23-May-2016

11:29 - 11:29

Time after HW:

7:09

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_025.csv

Transect ID:

013



Date/time:

14-Jun-2016

10:56 - 10:58

Time after HW:

0:17

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_026.csv

Transect ID:

013



Date/time:

28-Jun-2016

10:54 - 10:55

Time after HW:

1:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_027.csv

Transect ID:

013



Date/time:

13-Jul-2016

11:08 - 11:09

Time after HW:

1:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_028.csv

Transect ID:

013



Date/time:

25-Jul-2016

12:23 - 12:24

Time after HW:

5:14

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_029.csv

Transect ID:

013



Date/time:

09-Aug-2016

10:59 - 11:00

Time after HW:

3:29

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_030.csv

Transect ID:

013



Date/time:

23-Aug-2016

10:53 - 10:54

Time after HW:

4:04

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_031.csv

Transect ID:

013



Date/time:

06-Sep-2016

11:15 - 11:16

Time after HW:

4:56

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_031.csv

Transect ID:

013



Date/time:

06-Sep-2016

11:16 - 11:16

Time after HW:

4:56

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_032.csv

Transect ID:

013



Date/time:

20-Sep-2016

11:02 - 11:03

Time after HW:

5:13

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_033.csv

Transect ID:

013



Date/time:

18-Oct-2016

11:25 - 11:26

Time after HW:

6:56

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

T_013_035.csv

Transect ID:

013



Date/time:

13-Dec-2016

12:17 - 12:19

Time after HW:

-2:21

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_018.csv

Transect ID:

015



Date/time:

20-Jan-2016

08:19 - 08:20

Time after HW:

-4:40

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_019.csv

Transect ID:

015



Date/time:

17-Feb-2016

08:24 - 08:24

Time after HW:

1:54

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_020.csv

Transect ID:

015



Date/time:

16-Mar-2016

08:19 - 08:21

Time after HW:

-1:29

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_021.csv

Transect ID:

015



Date/time:

06-Apr-2016

07:20 - 07:21

Time after HW:

4:21

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_021.csv

Transect ID:

015



Date/time:

06-Apr-2016

07:20 - 07:22

Time after HW:

4:21

I/RA/11459/xx.xxx/yyyy

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_022.csv

Transect ID:

015



Date/time:

20-Apr-2016

06:55 - 06:57

Time after HW:

3:26

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_022.csv

Transect ID:

015



Date/time:

20-Apr-2016

06:56 - 06:57

Time after HW:

3:26

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_023.csv

Transect ID:

015



Date/time:

11-May-2016

07:35 - 07:37

Time after HW:

0:06

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_025.csv

Transect ID:

015



Date/time:

15-Jun-2016

07:51 - 07:51

Time after HW:

0:21

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_026.csv

Transect ID:

015



Date/time:

29-Jun-2016

07:20 - 07:21

Time after HW:

-3:29

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_027.csv

Transect ID:

015



Date/time:

14-Jul-2016

07:23 - 07:24

Time after HW:

1:04

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_029.csv

Transect ID:

015



Date/time:

10-Aug-2016

07:16 - 07:17

Time after HW:

-1:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_030.csv

Transect ID:

015



Date/time:

24-Aug-2016

07:26 - 07:27

Time after HW:

-1:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_031.csv

Transect ID:

015



Date/time:

07-Sep-2016

07:23 - 07:24

Time after HW:

-0:16

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_032.csv

Transect ID:

015



Date/time:

21-Sep-2016

07:14 - 07:15

Time after HW:

-0:05

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_033.csv

Transect ID:

015



Date/time:

19-Oct-2016

07:35 - 07:36

Time after HW:

1:25

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Dendermonde

Equipment:



ADCP

Sourcefile:

T_015_035.csv

Transect ID:

015



Date/time:

14-Dec-2016

08:29 - 08:31

Time after HW:

4:30

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_018.csv

Transect ID:

018



Date/time:

20-Jan-2016

09:50 - 09:51

Time after HW:

-3:39

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_019.csv

Transect ID:

018



Date/time:

17-Feb-2016

09:46 - 09:47

Time after HW:

2:37

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_020.csv

Transect ID:

018



Date/time:

16-Mar-2016

09:38 - 09:38

Time after HW:

-0:51

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_021.csv

Transect ID:

018



Date/time:

06-Apr-2016

09:07 - 09:08

Time after HW:

5:27

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_022.csv

Transect ID:

018



Date/time:

20-Apr-2016

08:38 - 08:39

Time after HW:

4:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_023.csv

Transect ID:

018



Date/time:

11-May-2016

09:05 - 09:07

Time after HW:

0:56

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_025.csv

Transect ID:

018



Date/time:

15-Jun-2016

09:25 - 09:26

Time after HW:

-3:43

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_026.csv

Transect ID:

018



Date/time:

29-Jun-2016

08:55 - 08:56

Time after HW:

2:16

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_027.csv

Transect ID:

018



Date/time:

14-Jul-2016

08:58 - 08:59

Time after HW:

1:48

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_029.csv

Transect ID:

018



Date/time:

10-Aug-2016

08:44 - 08:45

Time after HW:

-0:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_029.csv

Transect ID:

018



Date/time:

10-Aug-2016

08:45 - 08:45

Time after HW:

-0:44

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_030.csv

Transect ID:

018



Date/time:

24-Aug-2016

08:53 - 08:54

Time after HW:

-0:06

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_031.csv

Transect ID:

018



Date/time:

07-Sep-2016

08:58 - 08:58

Time after HW:

0:38

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_032.csv

Transect ID:

018



Date/time:

21-Sep-2016

08:52 - 08:52

Time after HW:

1:02

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_033.csv

Transect ID:

018



Date/time:

19-Oct-2016

09:28 - 09:29

Time after HW:

2:39

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Uitbergen

Equipment:



ADCP

Sourcefile:

T_018_035.csv

Transect ID:

018



Date/time:

14-Dec-2016

10:37 - 10:39

Time after HW:

5:58

I/RA/11459/17.034/YDK

Data Processed by:



1.2. Resultaten van de 13-uursmetingen

1. Kruibeke, Terhagen en Schoonaarde

Tijcyclus

Meet- jaar mm-jj	Dieptegemiddelde Kruibeke							Dieptegemiddelde Terhagen							Dieptegemiddelde Schoonaarde						
	Tij- coeff.	QSchel [m³/s]	SPM [mg/l]	Snelh [m/s]	Netto Watvol [10³m³]	Netto SSL [ton]	Duur [u:m]	Tij- coeff.	QRup.[m³/s]	SPM [mg/l]	Snelh [m/s]	Netto Watvol [10³m³]	Netto SSL [ton]	Duur [u:m]	Tij- coeff.	QMel [m³/s]	SPM [mg/l]	Snelh [m/s]	Netto Watvol [10³m³]	Netto SSL [ton]	Duur [u:m]
05-11	1.16	34	609	0.89	3.10³	6.10³	-	1.12	13	186	0.93	2.10³	321	-	1.08	7	193	1.07	755	-147	-
04-12	1.06	87	229	0.86	-	-	-	1.11	49	179	0.71	13	5	12:34	1.12	26	93	0.57	22	2	12:24
05-13	1.06	101	184	0.72	-46	-17	12:57	1.09	55	73	0.78	-	-	-	1.16	31	66	0.36	-	-	-
07-14	1.01	85	120	0.81	1	-4	12:09	1.05	45	138	0.77	4	-4	12:14	1.16	28	236	0.72	9	5	12:05
06-15	1.07	47	126	0.70	0.7	-1	12:20	1.07	27	199	0.80	-43	-12	12:30	1.11	13	149	0.65	16	1	12:35
06-16	1.07	265	167	0.79	70	5	12:26	1.04	136	153	0.77	43	8	12:23	1.10	84	55	0.69	34	1	12:29

Ebfase

Meet- jaar mm-jj	Dieptegemiddelde Kruibeke						Dieptegemiddelde Terhagen						Dieptegemiddelde Schoonaarde					
	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]
05-11*	1.16	637	0.86	70.10²	49.10³	-	1.12	189	0.82	8.10³	1.10³	-	1.08	188	1.01	3.10³	0.5.10³	-
04-12	1.06	219	0.88	-	-	-	1.11	206	0.77	61	12	7:32	1.12	99	0.63	64	7	7:40
05-13	1.06	149	0.75	90	13	6:29	1.09	85	0.91	-	-	-	1.16	63	0.40	-	-	-
07-14	1.01	107	0.92	149	16	6:24	1.05	112	0.86	67	7	6:44	1.16	263	0.66	62	17	6:46
06-15	1.07	123	0.74	121	16	6:40	1.07	182	0.83	47	8	7:06	1.11	147	0.64	69	10	7:41
06-16	1.07	145	0.85	224	34	6:48	1.04	178	0.96	82	13	7:28	1.10	56	0.72	96	6	7:57

Vloedfase

Meet- jaar mm-jj	Dieptegemiddelde Kruibeke						Dieptegemiddelde Terhagen						Dieptegemiddelde Schoonaarde					
	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]	Tij-coeff.	SPM [mg/l]	Snelh [m/s]	Wat.vol [10³m³]	SSL [ton]	Duur [u:mm]
05-11*	1.16	578	0.91	67.10³	44.10³	-	1.12	181	1.11	6.10³	1.10³	-	1.08	200	1.15	3.10³	0.6.10³	-
04-12	1.06	248	0.83	-	-	-	1.11	149	0.63	48	7	5:01	1.12	82	0.46	42	4	4:43
05-13	1.06	216	0.70	136	31	6:27	1.09	60	0.64	-	-	-	1.16	73	0.29	-	-	-
07-14	1.01	131	0.72	148	20	5:45	1.05	172	0.66	63	11	5:29	1.16	207	0.79	53	11	5:19
06-15	1.07	130	0.64	121	17	5:39	1.07	220	0.75	90	20	5:23	1.11	154	0.67	53	9	4:53
06-16	1.07	195	0.71	154	29	5:38	1.04	109	0.46	39	5	4:55	1.10	55	0.64	61	5	4:31

* Geen puntmeting maar een raaimeting waardoor de resultaten een gemiddelde zijn over de meetraai.

1.3. Raaimetingen aan GGG-Lippenbroek

Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2001T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:18 - 07:22

Time after HW:

-0:59

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2001T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:23 - 07:26

Time after HW:

-0:55

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2002T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:31 - 07:35

Time after HW:

-0:46

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2002T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:35 - 07:39

Time after HW:

-0:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2003T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:46 - 07:49

Time after HW:

-0:31

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2003T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:50 - 07:54

Time after HW:

-0:27

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2004T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:55 - 07:59

Time after HW:

-0:22

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2004T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

07:59 - 08:03

Time after HW:

-0:18

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2006T_r1.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:10 - 08:14

Time after HW:

-0:07

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2006T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:14 - 08:18

Time after HW:

-0:03

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2007T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:19 - 08:22

Time after HW:

0:00

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2007T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:22 - 08:25

Time after HW:

0:04

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2008T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:26 - 08:30

Time after HW:

0:08

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2008T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:30 - 08:34

Time after HW:

0:12

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2010T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:51 - 08:54

Time after HW:

0:32

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2010T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

08:54 - 08:59

Time after HW:

0:37

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2011T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:00 - 09:03

Time after HW:

0:42

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2011T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:04 - 09:07

Time after HW:

0:45

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2012T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:08 - 09:11

Time after HW:

0:49

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2012T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:11 - 09:16

Time after HW:

0:54

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2013T_rl.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:17 - 09:20

Time after HW:

0:59

I/RA/11459/17.034/YDK

Data Processed by:



Onderzoek Milieu-Effecten Sigmaplan (OMES)

Location:

Lippenbroek

Equipment:



ADCP

Sourcefile:

2013T_lr.csv

Transect:

Kil - Scheldt



Date/time:

19-Jan-2017

09:22 - 09:25

Time after HW:

1:03

I/RA/11459/17.034/YDK

Data Processed by:



